STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING: 01 B, WING FCL011223 02/11/2015 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 236 COUNTRY TIME CIRCLE EVERGREEN LIVING HOME #10 LEICESTER, NC 28748 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (X5) COMPLETE (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE PREFIX CROSS-REFERENCED TO THE APPROPRIATE TAG REGULATORY OR LSC IDENTIFYING INFORMATION) TAG DEFICIENCY) (C 000) Initial Comments (C 000) CONSTRUCTION SECTION Report by Glerin Hoppin MAR 3 0 2015 A Complaint Follow-up Survey was conducted on February 11, 2015 starting at 10:45AM and RECEIVED ending at 11:15AM. Not all of the previously cited deficiencies were corrected. Therefore, further action is required. The remaining deficiencies that were observed are as follows: C 150 Outside Entrances/Exits-Wanderers, Alarms C 150 SECTION .0300 - THE BUILDING 10A NCAC 13G .0312 OUTSIDE ENTRANCE AND EXITS (g) In homes with at least one resident who is determined by a physician or is otherwise known to be disoriented or a wanderer, each exit door for resident use shall be equipped with a sounding device that is activated when the door is 2/19/16 3 door alam. provided opened. The sound shall be of sufficient volume that it can be heard by staff. If a central system of remote sounding devices is provided, the control panel for the system shall be located in the bedroom of the person on call, the office area or in a location accessible only to staff authorized by the administrator to operate the control panel. This Rule is not met as evidenced by: The wander alarm in the facility is not working. A plan of protection is in place until the alarm is repaired. Have a qualified individual repair or replace the wander alarm. C 161 Housekeeping-Land Line Phone C 161 SECTION .0300 - THE BUILDING Division of Health Service Regulation

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

Administrator

If continuation sheet

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA

AND PLAN OF CORRECTION		IDENTIFICATION NUMBER:	A BUILDING	LE CONSTRUCTION ≥ 01		COMPLETED	
					,	۹ ا	
		FCL011223	B. WNG		02/1	1/2015	
NAME OF	PROVIDER OR SUPPLIER	STREET AD	DRESS, CITY.	STATE, ZIP CODE			
EVERGE	REEN LIVING HOME #	10	TRY TIME R, NC 287				
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES  MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOU CROSS-REFERENCED TO THE APPRO DEFICIENCY)	LD BE	(XS) COMPLETE DATE	
C 161	Continued From page	ge 1	C 161	,			
	10A NCAC 13G .03 FURNISHINGS (a) Each family car (12) have at least of depend on electricity operate. (e) This Rule shall homes.  This Rule is not me 1.) At the time of surthere is no landline.	15 HOUSEKEEPING AND re home shall: one telephone that does not y or cellular service to apply to new and existing		provided landing	<u>L</u> Nkoni	3/20/15	
(C 170)		far service to operate.	(C 170)				
-	DISASTER PLAN (c) Any fire safety s	HE BUILDING 16 FIRE SAFETY AND requirements required by city y building inspectors shall be					
	County Fire Marshal Construction Section	conducted with the Buncombe is office, DSS, and the DHSR					
	The following conditi	ons were observed					
		ne 911 dispatcher was unable aff member calling, because eaks only Korean.					
		was turned of to the facility , the phones, and the wander					

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X3) DATE SURVEY (XZ) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING: 01 B. WING FCL011223 02/11/2015 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 236 COUNTRY TIME CIRCLE EVERGREEN LIVING HOME #10 LEICESTER, NC 28748 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X5) COMPLETE (X4) ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PRÉFIX PREFIX DATE CROSS-REFERENCED TO THE APPROPRIATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) (C 170) Continued From page 2 (C 170) alarm did not function. Based on these facts the Buncombe County fire Company will submit the plan to the firemorphall

will be installed Marshall is requiring an addressable monitored fire alarm system that will tell emergency responders what the emergency is and where to respond. Obtain bids for a monitored addressable fire alarm system and provide the Buncombe County Fire Marshals office and the DHSR Construction section with a set of installation drawings for approval before installing the nuch week. system. Provide the DHSR Construction section with copies of all permits, plans, invoices, and any other supporting documentation when the system is complete. Contact the Fire Marshals office and the DHSR Construction section for final approval after installation.



## SCHEDULE OF PROTECTION

hick,

The ADT Authorized Dealer Program is an ADT LLC dba ADT Security Services ("ADT") approved Program of independent ADT Authorized Dealers, Please refer any questions: concerning the Program or Dealer to ADT at 800-539-9880.

Monitoring /	Account	Number
--------------	---------	--------

Dealer Name Dealer Number: (6.77225

Γ.	いか しょりラジニブ	
e	Protect Your Home	_
	6.3-2262	_

TH	IIS CONTRACT is made and entered into this	dev	of Vety	rate.	C. 20 (5" by and hopeon Donlar	το;	Gfle	ип. Норрій
CV	Ve" "Us" or "Our") and \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	·		24.9				
_	IS CONTRACT is made and entered into this	(")	donitored Lo	catle	(100 or 100 or 100 or 100 or 100	r.),		
Th	Street & Number, State, Zip Code				Home Telephone B	usinese Tolap	hore	٠,
co	is Schedule of Protection is Incorporated by reference additions of which fully apply to this Schedule of Prote	e inco (ne ction.	Alarm Serv	ices	Contract made this date between We, the	Dealer a	nd You, the	terms and .
	of present and	OMMER	CIAI	_	>∂ WIRELESS		E ADIOT	1 4 CO 1 CO
	DESCRIPTION	CHINETO		_	XQ WINELESS		□ APART	
	Base System (\$850 Value)- SELECT ONLY ONE OF THE	FOLLOWII	WG		· · · · · · · · · · · · · · · · · · ·		Price	EXTENDED PRICE
	☐ Impassa Base (1 Key, 2 D/W, 1 Motion)							
	Power Series (1884 Panel, 1 Keypad, 1 Keyfob)				-		\$_99.00	1 90 v
		WIRELESS 2 Boot/Window 1 Motion Keyped						11.00
	PROMO ITEM						\$49	
						PRE INST.	ALL SUBTOT	AL OOLO
	Pulse Sciect Wireless		í					
	Pulsa Select Hardwire (I-Hub, IT230)						\$15	
	Pulse + Vidao Wireless (I-Hub, 1 Wireless Keypad, C	ellular U	alt 1 Indoor	Com	and a		\$29	-
	Pulse + Video Hardwire (I-Hub, IT230, 1 Indoor Came	era)	ing i indoor	call	rere,		\$35	
			ellulare ( t = 14 - 1		and and discourse to the state of		\$45	
	Pulse + Home Control Wireless (I-Hub, 1 Wireless K Pulse + Home Control Hardwire (I-Hub, IT230, 1 Doo	eypad, Ci	Mular Unit,	Do	or Lock, 1 Lamp/Appliance Control)		\$49	19
							\$59	19
	Pulse + Video & Home Control Wireless (I-Hub, 1 Wire Pulse + Video & Home Control Hambeiro (I-Hub, 1733	O. 4 Inde	ad, Cellular U	nit, 1	Indeer Camers, 1 Door Lock, 1 Lamp/Appllan	ce Control)	\$59	
	Pulsa + Video & Home Control Hardwire (i-Hub, IT23	u, 1 Indo	or Camera, 1	Doc	or Lock, 1 Lamp(Appliance Control)		569	9
OT I	TEMS NOT USED Keychain Remore(\$129)					PUI	SE SUBTOT	AL
u i i	TEMS NOT USEDKeychain Remote(\$129)	Door	/Window(S1	29)	Motion Detector(\$229)			
			4484					
YT)	Equipment	Tester			ection Devices		,	
$\overline{}$	Integrated Cellular Unit	S99 ea.	Total Price	QIY.	Equipment		Price	Total Price
	Cellular Unit 36 2075 36 3070 TG-4 (circle one)	599 to.	11.00	Н	Indoor Camera Outdoor Camera		5229 ea. 5289 ea.	
_	Wireless Door/Window Sensor	5129 ea.	179.00	_	Wi-Fi Repeater		5169 ea.	
	Keychain Remote (w/Personal Panic)		-		Ethernet Switch	549 en.		
	2-Way Keychain Remote	51/09 ee.			8 Zone DSC Translator	569 ex.		
-	Wireless Motion Detector	\$229 au.	-		GE Wireless Translator	\$69 ea.		
i	Wireless Shock Detector Wireless Smoke Communicator (Monitored Phoso-Electric)	5149 ea.		_	Honeywell/2. Glg Translator		569 ea.	
-	Wireless Glass Break Detector	\$229 ea.	220.00	⊢	Powerline Adapter		\$249 ex.	+
	Wireless Carbon Monoxide Desactor	\$229 ea.	+	Н	Hardwire Glass Break Detector Hardwire Doon/Window Contect		5229 ea.	
-	Emergency Pendant	\$129 42.	224.60	Н	Hardwire Indoor Stren		\$129 ea. \$149 ea.	+
_	Wireless 2-Wey Keypad (Impassa)	5249 ea.		_	Hardwire Motion Detector		5229 ga.	_
	Deak Stand for Wireless 2-way Keypod				Hardwire Smoke Communicator	5129 ea.		
	Wireless Overheed Sarage Door Sensor	\$149 es.			Hardwire Touchpad (Power Series)		\$229 40	
	Vanishing Contact Wireless Indoor Siren	\$149 ea.	-	$\vdash$	Power Series Z Wey Volce Module and Speaker, 2 Po	orts	\$149 ma.	
-	Wireless Indoor Siren Wireless Exterior Siren with Temp Sensor and Strobe	\$149 cc. \$289 cc.	+	⊢	Door LockBrassNickelGroups		\$229 02.	_
_	Wireless Flood Sensor	5149 ea.	+	$\vdash$	Lamp/Appliance Control Thermostat		569 ea. 5149 ea.	
-	Repeater Kit	5229 ep.		Н	THE THOUSEN		3147 Rp.	-
		1		1	EC			35800
					s			\$73.00
					Dr .			\$73-0c.
						IN	STALL SUBTOT	
- 12	2-17- DATE V	F 7 ' '	PURCHASER	s sic	GNATURE	SUBT	OTAL	7000
	INSTALLATION DATE GIVEN INSTALLATION TECHNICIAN NAME				% TAX	693		
(	DEALER LICENSE NUMBER  (177.27 2				TAL	4/593		
	LESS DES					EPOSIT	/ <sub>U</sub> S_83	
/er 3	13.7.14 PULSE NL CUSTOMER COPY.						SEDUE 3	800.00